

### Sunshine Oilsands Ltd. BA Code A2TF

阳光油砂 SUNSHINE OILSANDS LTD.

#### **WEST ELLS SAGD**

Scheme No. 11764G
AER In Situ Performance Presentation
June 30, 2021

#### 阿光注砂 SUNSHINE OIL SANDS LTD.

#### **Table of Contents**

- 1. Introduction
- 2. Subsurface
- 3. Surface
- 4. Historical and Upcoming Activity



## Introduction



#### **Location within the Athabasca Oilsands Deposit**


**West Ells SAGD Project** Birch Mountain Located in the NW part of the Athabasca Oilsands Deposit, Alberta, Canada **West Ells** Athabasca Oilsands Deposit

http://osip.alberta.ca/map/



#### **West Ells SAGD**

- Covering 9,856 contiguous gross hectares in the Athabasca Oil Sands Region
- Two phases of 5,000bbl/d
  - Phase 1 currently in Operation since September 2015 is supplied by Pad 2
  - Phase 2 will commence in the future and is supplied by Pad 3 which has been drilled
  - ➤ MSL 112941 and MSL 112933 were cleared of vegetation with no soil disturbance, anticipated to serve as make-up pads as the project advances






## Subsurface




#### **Production Curves**






#### **Annotation of Major Events**





#### **Development and Project Area**




Area	Land Description
Development Area (4 sections)	T94 R17W4; Sec 30, 31 T94 R18W4; Sec 25, 36
Project Area (6 sections)	T94 R17W4; Sec 30, 31, 32, 33 T94 R18W4; Sec 25, 36

First Steam – September 2015

First Production – December 2015



#### **West Ells Pad & Well Locations**



SAGD Well Pair – Drilled & Completed

SAGD Well Pair – Drilled, liners installed, pump and instrumentation install not complete.


Source Water Well – Drilled & Completed



#### Typical SAGD Well Placement (e.g. Pair 8)

So = 83.0%

Porosity = 34.9%






Producer

Bottom 268.75 m




#### **Stratigraphic Chart & Type Well**

#### Stratigraphic chart




Type Well – OB41 (102/06-31-094-17W4)



The SAGD wells are located at the base of the Wabiskaw D sand unit




#### **Top of Bitumen Pay Structure Map**






#### **Base of Bitumen Pay Structure Map**






#### Wabiskaw C Top Gas Isopach Map






#### Wabiskaw D Lean Zone Isopach Map






#### **Geomechanical Anomalies - Cap Rock Integrity**

- No geomechanical anomalies reported in 2020 as the injection pressure was below MOP\*. The injection pressure before shut-in was between 1750 and 2100 kPa
- Mini-frac tests were performed at:
  - > 1AA/14-31-094-17W4/0
  - > 1AA/07-36-094-18W4/0
- Caprock average minimum stress gradient = 22 kPa/m (Wabiskaw Shale Member)






<sup>\*</sup> The maximum operating pressure (MOP) of **4400** kPag was granted on March 10, 2016



#### **Geomechanics -** Caprock and Oil Sand from 14-31-94-17W4 Location






#### 3D Seismic Survey and Acquisition Parameters

No new seismic data acquired in this reporting period

#### **Survey Layout**



#### **Acquisition Parameters**

<b>Area</b> 10.7 (km <sup>2</sup> )				
Source Information		Receiver Information		
Source interval (m)	20	Receiver interval (m)	20	
Source line interval (m)	80	Receiver line interval (m)	60	
Line orientation	N-S	Line orientation	W-E	
Total km of line	167.1	Total km of line	194.9	
Number of source points	7078	Number of receiver points	9681	
Source depth (m)	6			
Source type	Dynamite			





#### 4-D Seismic

- As measured on the observation wells, the width of the steam chamber is narrow and less than 10 m from the SAGD well pair. Therefore, Sunshine did not plan a 4D seismic acquisition survey in 2020 because it is difficult to image a small steam chamber in the seismic data
- While there are no plans in 2021 to conduct a 4D seismic survey, Sunshine will consider a 4D seismic survey when it is appropriate and provides an advantage for resource recovery



#### **Cross-Section A-A' of the Active Development Area**







#### **OBIP for Pads 2 & 3 and Development Area**


	Number of SAGD Well Pairs	Drainage Area 50m Boundary	Average Net Pay above producer	Total OBIP	Producible Bitumen in Place	Cumulative Bitumen Produced*	Current Recovery Factor	Estimated Recovery Factor
		(10 <sup>3</sup> m <sup>2</sup> )	(m)	(10 <sup>6</sup> m <sup>3</sup> )	(10 <sup>6</sup> m <sup>3</sup> )	(m³)	(%)	(%)
Pad 2	8	504	16.2	1.87	1.12	315,981	16.9	50-60
Pad 3	8	504	15.4	1.86	1.12	0	0	50-60

#### \*Production to December 31, 2020

	Area	Average Net Pay	Total OBIP	
	(10 <sup>3</sup> m <sup>2</sup> )	(m)	(10 <sup>6</sup> m <sup>3</sup> )	
<b>Development Area</b>	10,511	15.2	37.2	
Project Area	15,734	14.7	53.7	

OBIP = Area x Net Pay x Porosity x Bitumen Saturation / FVF

FVF = Formation Volume Factor = 1.005





#### **Average Reservoir Properties for Development Area**

Property	Value
Bitumen saturation (%)	71
Porosity (%)	33
Grain size	Fine to medium
Net pay (m)	15.2
Horizontal perm. (D)	2.4
Vertical perm. (D)	1.7
Reservoir pressure (kpa)	600
Reservoir temperature (°C)	9
Reservoir depth (m TVD)	265
Bitumen viscosity (cp)	> 1 million
Well length (m)	800
Well spacing (m)	70




## Surface




#### **CPF Plot Plan**

· No major facility modifications during this reporting period






#### **Bitumen Production**





#### **Steam Injection**






# Historical & Upcoming Activity



#### **Summary of Suspension Activity**

- Pad 2 (WP11):
  - ➤ Has been suspended since May 1, 2019 and this suspension impacted production from well pairs 10 and 12
  - > It was not economic to fix the well in 2020
  - ➤ 226,723 m³ of remaining reserves
- Pad 2 (Temporarily suspended)
  - → 4 ESPs will be replaced in Q3 2021
  - Production will resume in Q4 2021





#### **Regulatory and Operational Changes**

Date	Approval/Amendment	Activity
May 29, 2020	EPEA Approval No. 00266890	Authorization request related to COVID-19 – environmental monitoring relaxation
July 20, 2020	EPEA Approval No. 00266890	Authorization request for environmental monitoring variance
July 23, 2020	WA Licence No. 00316770	Renewal submission extension

#### Notes

o EPEA – Environmental Protection and Enhancement Act Approval

o WA - Water Act



#### **Regulatory and Operational Changes**

#### In this reporting year there were:

- Unprecedented market volatility and the economic uncertainty associated with the ongoing COVID-19 pandemic that resulted in the temporary suspension of production in April 2020
- This materially affected scheme performance, energy or material balances
- No technological innovations or pilots were conducted



#### **Lessons, Success and Failures**

- There were no major failures/incidents reported at the site
- 2020 was a challenging year for the Industry, Sunshine and West Ells.
   Despite the pandemic and difficult market conditions, West Ells successfully reduced its operating cost by suspending production
- Operating West Ells with no bitumen production and reduced staff proved to be a challenge. The team successfully maintained West Ells in good condition so production can resume in 2021
- The lack of continuity in knowledge and experience due to reduced staff has impacted the smoothness of operation. Sunshine can learn and improve from this experience
- Communication is the key to success. Sunshine's staff work closely together to overcome challenges and adversities



#### **Compliance History – Approval Contraventions**

 The following list summarizes non-compliance events and two reportable releases in this reporting period

Date	CIC#	Description	Remediation
03-Feb	0363344	Failed to submit December 2019 CEMS data on time	Data has been submitted
17-Feb	0363784	Third Party truck and trailer rolled over into the ditch when leaving the site, releasing approximately 3.5m³ of Evaporator Blowdown Water	Truck and trailer were removed, cleanup activities were completed and confirmatory sampling confirmed soil endpoints were within referenced Alberta Tier 1 Soil Remediation Guidelines
02-Mar	0364205	Failure to submit January 2020 CEMS data on time	Data has been submitted
01-Apr	0364977	Failed to submit February CEMS data, passive air monitoring data and the 2019 Annual Industrial Air Monitoring Report on time	Data and reports have been submitted
24-Apr	0365697	An erosion channel had formed under the ice on the surface of the well pad and an uncontrolled release of surface run-off water into the environment occurred	A temporary patch to the well pad berm was installed
01-Dec	0374114	Failure to submit the second Soil Monitoring Report by December 1, 2020	Variance was received and report will be submitted by December 1, 2021



#### **Future Plans**

- Sunshine plans to resume production in Q4 2021
- No new initiatives planned within the next 5 years
  - ➤ Continue to fully demonstrate the reservoir productivity before advancing to Phase II (10,000 bpd production)
- EPEA Approval (266890) renewal application expected to be submitted in July 2021



Sunshine Oilsands Ltd.

1100, 700 – 6<sup>th</sup> Ave SW

Calgary, AB T2P 0T8

(403) 984-1450

info@sunshineoilsands.com



阳光油砂 SUNSHINE OILSANDS LTD.