


<p>MADE at the City of Calgary, in the Province of Alberta, on</p> <p>25th day of February 2010.</p>	 <p>ENERGY RESOURCES CONSERVATION BOARD</p>
--	---

The Energy Resources Conservation Board (ERCB) pursuant to the Oil and Gas Conservation Act, chapter O-6 of the Revised Statutes of Alberta, 2000, orders as follows:

- 1) The following table shows the specified pools and wells in the **Lawrence Field** wherein production may be commingled in the wellbore:

Pools	Wells (Unique Identifier)
Lawrence Belly River A, Lawrence Belly River B, Lawrence Upper Mannville C, Lawrence Upper Mannville D, Lawrence Upper Mannville G, and Lawrence Ellerslie B	00/03-31-041-12W5
Lawrence Belly River C Pool, Lawrence Upper Mannville J Pool, Lawrence Glauconitic B Pool, and Lawrence Ellerslie G Pool	00/07-14-042-12W5

- 2) In the event that the Belly River pools approach 90% of the fracture pressure, EnCana Corporation is required to mechanically isolate the Upper Mannville and Ellerslie pools from the Belly River pools in the 00/03-31-041-12W5 well, and mechanically isolate the Upper Mannville, Glauconitic and Ellerslie pools from the Belly River pool in the 00/07-14-042-12W5 well.
- 3) Gas production from the Belly River with zones in the DE 2 Strata (Smoky to the Base of Rock Creek Formations) may be taken without segregation in the wellbore from the wells located in the following areas¹:

IN TOWNSHIP 42, RANGE 12, WEST OF THE 5TH MERIDIAN:
 Sections 1 to 3 inclusive, Section 5 and 6, Sections 10 to 15 inclusive, and Sections 23, 26, 27, and 34
 IN TOWNSHIP 43, RANGE 11, WEST OF THE 5TH MERIDIAN:
 Sections 6

- 4) Operators shall conduct a segregated initial and annual pressure test on the first new well completed in the Belly River and Lower Cretaceous zones in the NE and SW quarters of Township 42-12W5 as outlined in clause 3. Operators shall also conduct a segregated annual pressure test in the Belly River and Lower Cretaceous zones on 00/07-14-042-12W5, 00/15-18-043-12W5, 00/03-02-043-12W5 wells located in area outlined in clause 3.¹
- 5) Board Order No. MU 7196 is rescinded.

END OF DOCUMENT